

Door Interface

Revision Notes

Version 1.0.2

English
EN 301.00.DI24

Firmware Version 1.0.2 (Build No. 1.0.2_250924)

Release: 2025-10-21

Bug Fixes

1. CPU usage rises to as high as 100%. (Affects version: v1.0.0)

Firmware Version 1.0.1 (Build No. 1.0.1_250625)

Release: 2025-06-26

Bug Fixes

1. The door relay operates abnormally when the connection to the master device is lost. (Affects version: v1.0.0)
2. When a specific device is connected as a slave, configuration changes are not properly applied.
(Affects version: v1.0.0)
3. Slave devices are intermittently not detected or get disconnected. (Affects version: v1.0.0)
4. The **Custom Smart Card Layout** set on the slave device is not displayed properly on the device detail page.
(Affects version: v1.0.0)

Firmware Version 1.0.0 (Build No. 1.0.0_250509)

Release: 2025-05-15

Initial Firmware Developed.



Suprema Inc.

17F Parkview Tower, 248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 13554, Rep. of KOREA
Tel: +82 31 783 4502 | Fax: +82 31 783 4503 | Inquiry: sales_sys@supremainc.com



For more information about Suprema's global branch offices,
visit the webpage below by scanning the QR code.
<https://supremainc.com/en/about/global-office.asp>

© 2025 Suprema Inc. Suprema and identifying product names and numbers herein are registered trade marks of Suprema, Inc.
All non-Suprema brands and product names are trademarks or registered trademarks of their respective companies.
Product appearance, build status and/or specifications are subject to change without notice.